

States
ent of
ure

Forest
Service

Humboldt N. F.
Supervisor's Office

ADE-TECHNICAL

ADE-PROGRAMS

Benjamin

7460

Date: July 9, 1990


Subject: Asbestos Inspection Results

To: Regional Forester

As requested, asbestos inspections of the buildings on the Humboldt National Forest were performed and the results have been attached. This report is the comprehensive survey that you requested for fiscal year 1991. Since the buildings on our Forest are so far apart, it was easier to do a comprehensive survey than to do the preliminary assessment that you requested to be submitted by July 1, 1990.

As a general summary, there were 118 buildings inspected for the asbestos indicators and 34 of the buildings had one or more of these indicators. The breakdown of these results by district is as follows:

DISTRICT	No. OF BUILDINGS INSPECTED	No. BUILDINGS WITH ASBESTOS INDICATORS
Mountain City	27	11
Ruby Mountain	23	6
Jarbridge	17	3
Ely	29	8
Winnemucca	16	3
Supervisor's Office	6	3
	118	34



E FILE COPY

If you have any questions, please feel free to call Laura Hamilton at 702-738-5171.

for Dale C. Armstrong
JOHN P. INMAN
Forest Supervisor

cc: Laura Hamilton
Districts

ELKO SUPERVISOR'S OFFICE

Forest: Humboldt National Forest
Ranger District: Supervisor's office
State & Location: 8th and Fir, Elko, Nv.
Forest Bldg No. 04091210
Type Construction: Frame
Use of Bldg Residence
Type ACMS Lath and Plaster walls and roof; 9x9 inch floor tile
Additional Comments: Built in 1946. Linoleum in kitchen and carpet in the living room. 9x9 inch floor tile in the basement. Wood siding on the house. POTENTIAL ASBESTOS IN THE LATH AND PLASTER WALLS AND ROOF AND THE FLOOR TILE.

Forest: Humboldt National Forest
Ranger District: Supervisor's office
State & Location: 8th and Fir, Elko, Nv.
Forest Bldg No. 04091302
Type Construction: Frame
Use of Bldg Warehouse
Type ACMS NONE
Additional Comments: Concrete floor with wooden walls and roof. Tin siding that is painted.

Forest: Humboldt National Forest
Ranger District: Supervisor's office
State & Location: 8th and Fir, Elko, Nv.
Forest Bldg No. 04091347
Type Construction: Frame
Use of Bldg Tire Shop
Type ACMS NONE
Additional Comments: Concrete floor with wooden walls and roof. Wood siding

Forest: Humboldt National Forest
Ranger District: Supervisor's office
State & Location: 8th and Fir, Elko, Nv.
Forest Bldg No. 04091348
Type Construction: Frame
Use of Bldg Gas house used to store lath and stakes
Type ACMS NONE
Additional Comments: Concrete floor with wooden walls and roof. Wood siding

Forest: Humboldt National Forest
Ranger District: Supervisor's office
State & Location: 8th and Fir, Elko, Nv.
Forest Bldg No. 04091349
Type Construction: Frame
Use of Bldg Shop
Type ACMS NONE
Additional Comments: Concrete floor with wooden walls and roof. There is a gas heater there without a backing.

Forest: Humboldt National Forest
Ranger District: Supervisor's office
State & Location: 8th and Fir, Elko, Nv.
Forest Bldg No. 04091351
Type Construction: Frame
Use of Bldg Carpentry
Type ACMS 9x9 inch floor tile;
Additional Comments: Carpentry shop consist of two parts: carpentry section and radio shop. Carpentry section: Concrete floor with wooden walls and roof. NO ASBESTOS. Radio Shop: There was a wood stove there at one time and there is brick backing there with a chimney stack that has been painted. The walls have plaster that could have asbestos. There is 9x9 inch floor tile and ceiling sections (16" by 32") that could have asbestos. The building has little white balls for insulation. POTENTIAL ASBESTOS IN THE FLOOR TILE, WALLS, AND CEILING.